



NOTE: IMPROPER SUPPORT OF KEEL FROM AFT END CAN CAUSE FRACTURE OF TAPE BOND AT JOINT AT FRONT OF KEEL

CATALINA YACHTS

21200 VICTORY BLVD.  
 WOODLAND HILLS, CA

SCALE: NONE

APPROVED BY:

DRAWN BY *GD*

DATE: 7-12-85

REVISED 5-20-96

KEEL CRACK REPAIR

DRAWING NUMBER

- 1